



Installation of the Howe Green

HSE 75 Aluminium Series




 Remove cover securing bolt and open cover using Lifting Key.




2 Attach Spring Brackets.





3 Position outer frame over pit, bedding on sand and cement, ensuring spring brackets are in contact with the vertical pit wall.

Drill holes in pit walls. Affix bracket against wall with **Rawl Bolt** and tighten **Securing Bolts**.




4 Close cover placing spacers between the cover and outer frame prior to filling and tiling.

Fill cover and tile surrounding area, ensuring that the infill has the equivelant strength of 40MPA concrete, when fully cured.

Fix Lifting Eyes to cover, using bolts supplied.

Open cover with Lifting Bar.



5 Open cover using Lifting Bar, attach Gas Springs as marked on spring.

>> CONTACT US

SAFE ACCESS ALL AREAS

Innovation Drive, Wolverhampton, West Midlands, WV9 5GA, UK

Sales Enquiries: +44(0)1920 463 230

Email: info@howegreen.co.uk

www.howegreen.com

